

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313183

Inspection Doc: 696206188

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313183



August 21, 2024



August 21, 2024

Photo 1: Photos 1-2 taken from the North end of the Location. Photos provide an overview from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313183



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313183



Photo 3: Photos shows Utility equipment on, and leading to, the Location has not been removed; utility equipment has been disconnected.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313183



Photo 4: Photo taken from the east end of the Location, facing east. Photos shows areas of the Location, including the access road to the Location, have not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313183



Photo 5: Photos shows the access road to the Location has not been reclaimed. Photo right example of culverts remaining along access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources




Photo 6: Google earth aerial imagery. Top photo dated 2023; bottom 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 2-11 did not pre-exist the Location.