

# Inspection Photos

08/21/2024

**Operator:** SWN PRODUCTION COMPANY LLC -  
10396

**Location ID:** 313152

**Inspection Doc:** 696206196

Moffat County, CO

Aaron Trujillo  
Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313152



August 21, 2024



August 21, 2024

**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview from west, northwest, northeast to east. Vegetation is progressing towards 1004 standards.,



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313152



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313152



**Photo 3:** Photo taken from the northeast end of the Location, facing west. Photo shows areas that may require additional seeding to meet 1004 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313152



**Photo 4:** Photo examples of Noxious weeds (Scotch thistle) observed on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313152



August 21, 2024



August 21, 2024

**Photo 5:** Photos show utility equipment on, and leading to, the Location has not been removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources