

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313327

Inspection Doc: 696206198

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



August 21, 2024

Photo 1: Photo taken from the east end of the Location, facing north. Photo shows utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



August 21, 2024

Photo 2: Photo taken from the Location entrance on the south end of the Location. Signage remaining on Location posted with incorrect Operator information.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



Photo 3: Photo taken from the east end of the Location, facing east. Photo shows areas of the Location that remain predominantly bare; areas are not progressing towards 1004.c.(2) standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



Photo 4: Photo examples of Noxious weeds (Scotch thistle) observed on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



Photo 5: Photos 5-6 show access road to the Location has not been reclaimed in accordance with 1004 Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313327



Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 7: Google earth aerial imagery. Top photo dated 2023; bottom 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the SARATOGA #44-3 did not pre-exist the Location.