

Inspection Photos

08/21/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313153

Inspection Doc: 696206200

Moffat County, CO

Aaron Trujillo
Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313153



Photo 1: Photos 1-2 taken from the southeast end of the Location. Photos provide an overview of the Location from southwest, northeast, north to northeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313153



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313153



Photo 3: Photos show utility equipment on, and leading to, the Location has not been removed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313153



Photo 4: Photos shows access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources




Photo 5: Google earth aerial imagery. Top photo dated 2023; bottom 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 3-2 not pre-exist the Location.