



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #1 sign on location

Sep 5, 2024 1:59:35 PM  
40.38546210620552N 107.40416773594916W  
680 West Washington Avenue  
Hayden  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

40.38535590749234N 107.404093304649W  
Sep 5, 2024 1:59:52 PM  
680 West Washington Avenue  
Hayden  
Routt County  
Colorado



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #2 ignition wire removed from pump.  
Note: oil on ground from open exhaust.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 9/5/2024

Photo #3 pipe coming off wellhead (presumed to be braden head) was measured with a handled PID. VOC's were detected coming out of open BH. It does not appear that a approval to vent gas has been requested or approved.

Sep 5, 2024 2:01:23 PM  
40.38534651976079N 107.40390638820827W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 9/5/2024

Photo #4 middle tank (of 3 AGT's) Note: oil on ground at base of tank.

Sep 5, 2024 2:02:59 PM  
40.38549990858883N 107.40428206510842W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #5 Green Tank is northernmost tank.

Sep 5, 2024 2:03:02 PM  
40.38549554999918N 107.40428047254682W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #6 South tank, this is the tank that had failed and was previously observed as leaking.

Sep 5, 2024 2:03:06 PM  
40.38549592718482N 107.40429346449673W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #7 South tank,  
area where tank was  
previously observed as  
leaking (Spilling)

Sep 5, 2024 2:03:18 PM  
40.38551038596779N 107.4043518025428W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #8 Area of impact inside secondary containment. It did not appear that fluid overtopped the secondary containment.

Sep 5, 2024 2:03:24 PM  
40.385508290492N 107.40435423329473W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Inspection Photos**

**Location Name: Dill Gulch 1-17**

**Location ID: 107-06019**

**Inspection Date: 9/5/2024**

Photo #9 Area of impact inside secondary containment. The white tank to the right of photo is a tank from a flatbed truck that is sitting inside of secondary containment. It is unknown if it is in use; it's not labeled or marked in any way.

Sep 5, 2024 2:03:36 PM  
40.38549990858883N 107.40444651804864W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #10 looking North  
across area of spill  
impact.

Sep 5, 2024 2:03:51 PM  
40.385569436475635N 107.40443830378354W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #11 close up of soil  
inside secondary  
containment. Note; oil  
staining and wildlife  
tracks.

Sep 5, 2024 2:04:02 PM  
40.38560946006328N 107.40439647808671W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #12 Spill area  
inside secondary  
containment. Note: soil  
staining.

Sep 5, 2024 2:04:08 PM  
40.385605855844915N 107.40440142340958W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #13 close up of soil  
inside secondary  
containment. Note; oil  
staining and wildlife  
tracks.

Sep 5, 2024 2:04:14 PM  
40.385605855844915N 107.40439287386835W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #14 close up of soil  
inside secondary  
containment. Note; oil  
staining and wildlife  
tracks.

Sep 5, 2024 2:04:17 PM  
40.385617967695N 107.40439589135349W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #15 photo taken  
from west side of  
secondary containment.  
Looking across area of  
impact.

Sep 5, 2024 2:04:22 PM  
40.3856116393581N 107.4044022615999W  
Unnamed Road  
Routt County  
Colorado



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Dill Gulch 1-17  
Location ID: 107-06019  
Inspection Date: 9/5/2024

Photo #

