

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 8/29/2024



Location Entrance – Photo #03235



Wellheads – Photo #03236

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 8/29/2024



Separators – Photo #03239



Tank Battery – Photo #03238

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 8/29/2024



Tank Battery – Photo #03240



Pit – Photo #03237

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S96W/24SENW

Location ID: 335485

Date: 8/29/2024



Spill Kit – Photo #03241



Open-Ended Load Line – Photo #03242