

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7645 From entrance to location



Photo # 7646 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7647 Location



Photo # 7648 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7649 Location



Photo # 7650 RMV 146-19 wellhead sign cracking & peeling/some required info starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7651 RWF 344-19 wellhead sign cracking & peeling



Photo # 7652 RWF 444-19 wellhead sign cracking & peeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7653 Battery sign cracking & peeling/some required info starting to become illegible



Photo # 7654 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7655 Improperly marked deadman



Photo # 7656 Same improperly marked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7657 Unmarked deadman



Photo # 7658 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 146-19 Pad

Location ID: 335345



Photo # 7659 Unused equipment