

**Operator: 8 North**

**Location Name: Purcell PC GK11-10**

**Loc ID: 419904**

**Inspection: 696301729**













**CA:** Unused Wellhead parts, chemical tanks, containment and stands.

**CA Resolution:** Operator has provided photo evidence to show that unused equipment has been removed to comply with the 600 series.

**CA:** Unmarked Risers. See photos. Corrective Action: Comply with Rule 603.f.

**CA Resolution:** Operator has marked identified risers appropriately to comply with the 600 series.