

**Operator: *Highpoint Operating Corp LLC***


**Location Name: Anschutz Equus Farms 3-62-4\_5 NENE**

**Loc ID: 447050**


**Inspection: 717700294**



**Exhibit A**




**Exhibit B**



**Exhibit C**



**Exhibit D**




**Exhibit E**



**Exhibit F**




**Exhibit G**



**Exhibit H**



**Exhibit I**



**Exhibit J**



**Exhibit K**



**Exhibit L**



**Exhibit M**



**Exhibit N**



**Exhibit O**



**Exhibit P**



**Exhibit Q**

**CA:** Pits around the location need to have capacity labels. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has addressed the issue. Future use tags have been installed on all unused risers and capacity labels on all pits have been replaced in order to comply with Rule 605.h.

**CA:** Unmarked Risers in multiple spots need to be marked. Comply with the 1100 rules

**CA Resolution:** Operator has addressed the issue. Future use tags have been installed on all unused risers and capacity labels on all pits have been replaced in order to comply with the 1100 series.