

Inspection Photos

Location: CAERUS PICEANCE LLC UWF/K04 596

Location ID: 335690

Date: 9/5/2024



Entrance to location - Photo #05436



Wellheads - Photo #05437

Inspection Photos

Location: CAERUS PICEANCE LLC UWF/K04 596

Location ID: 335690

Date: 9/5/2024



Wellhead missing signage - Photo #05441



Gas lift/Sales - Photo #05445

Inspection Photos

Location: CAERUS PICEANCE LLC UWF/K04 596

Location ID: 335690

Date: 9/5/2024



Tank battery/No signage - Photo #05449



SW corner of location - Photo #05455

Inspection Photos

Location: CAERUS PICEANCE LLC UWF/K04 596

Location ID: 335690

Date: 9/5/2024



SE corner of location - Photo #05457



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources