

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284




Photo 1 –Well placard on meter run.

Photo 2 – Wellhead and equipment.

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



Photo 3 – Meter house and equipment

Photo 4 – Pit Facility ID 280338, Pit permitted as an unlined pit

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



Photo 5 – Trees in NE corner of pit

Photo 6 – Engine skid

Inspection Photos
Location: Busch 42-30
Location ID: 308588
API # 05-071-08284



Photo 7 – Trees behind engine shed, exhaust is blowing on trees

Photo 8 – Trees in NE corner of pit