

Argali Exploration Company
McWilliams 2-31
Location ID: 312949



Inadequate containment



Unused equipment

Argali Exploration Company
McWilliams 2-31
Location ID: 312949



Unused equipment



Debris

**Argali Exploration Company
McWilliams 2-31
Location ID: 312949**



Location from Northeast corner



Location from Southeast corner

**Argali Exploration Company
McWilliams 2-31
Location ID: 312949**



Location from Southwest corner



Location from Northwest corner