

Inspection Photos

08/23/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313257

Inspection Doc: 696206219

Moffat County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313257



Photo 1: Photo taken from the intersection of the O&G access road, and the Surface Owner's road. Photo shows access road to the Location has not been reclaimed; gravel remains, road areas have not been decompacted and reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313257



August 23, 2024



August 23, 2024

Photo 2: Photos taken from the central areas of the Location. Vegetation within Location is predominantly Yellow Sweet clover, a biennial plant species. Noxious weeds (Scotch thistle) observed throughout the Location. It is noted that species planted do not reflect species within the adjacent undisturbed reference areas, or vegetation that existed pre-disturbance.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313257



Photo 3: Photo taken from the reference areas west of the Location.
Photo to compare vegetation between reference and disturbance areas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources