

# Inspection Photos

08/23/2024

**Operator:** SWN PRODUCTION COMPANY LLC -  
10396

**Location ID:** 313259

**Inspection Doc:** 696206221

Moffat County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313259



**Photo 1:** Photos taken from the east end of the Location, and provide an overview facing west and northwest.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313259



**Photo 2:** Photo shows O&G access road to the Location has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources