

Inspection Photos

08/23/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313258

Inspection Doc: 696206223

Moffat County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313258



Photo 1: Photos taken from the north end of the Location, facing southeast and southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313258



Photo 2: Weed establishment observed, though weed management efforts are evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313258



August 23, 2024

Photo 3: Photo taken from the adjacent reference areas west of the Location. Vegetation on the Location is not reflective of the reference.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313258

August 23, 2024



Photo 4: Photo shows signage remaining on Location posted with incorrect Operator information. Signage requires updating/maintenance or removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313258



Photo 5: Photos show O&G Access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources