

Inspection Photos

08/23/2024

Operator: SWN PRODUCTION COMPANY LLC -
10396

Location ID: 313256

Inspection Doc: 696206225

Moffat County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



Photo 1: Photos 1-2 taken from the central areas of the Location. Photos provide an overview of the Location from North, East, South to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



August 23, 2024



August 23, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



August 23, 2024



August 23, 2024

Photo 3: Photos example of Noxious (Scotch Thistle, Musk thistle) weeds observed established on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



Photo 4: Signage on Location posted with incorrect Operator information and has not been maintained. Sign requires updating/maintenance or removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



Photo 5: Photo taken from the intersection of CR 90 and the access road, facing east. Photo shows Access road/Location entrance has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



Photo 6: Erosion degradation evident along the unreclaimed access road.

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 313256



Photo 7: Shows culvert remaining at access road. Culvert requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources