

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9628 From Entrance to location



Photo # 9629 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9630 Location



Photo # 9631 Location



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad**  
**Location #: 334069**



**Photo # 9632 Location**



**Photo # 9633 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9634 Location



Photo # 9635 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9636 Location



Photo # 9637 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9638 Location



Photo # 9639 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9640 Location



Photo # 9641 Open ended load line



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 1-7 (G1SW) Pad

Location #: 334069



Photo # 9642 Tank battery lacks required signage



Photo # 9643