

Inspection Photos

September 9th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306851

Inspection Document #: 714001226

La Plata County, CO

Township: NWNW 21 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kennedy A2
Location ID: 306851



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Kennedy A2
Location ID: 306851



Photo 2. View of storm water controls in the western and northern portions of the cut slope that need maintenance.

Inspection Photos
Location Name: Kennedy A2
Location ID: 306851

9/9/24
+37.180604,-107.728968
234° SW



Photo 3. View of flowering musk thistle observed along the access road.

Inspection Photos
Location Name: Kennedy A2
Location ID: 306851



9/9/24
+37.180386,-107.733177
261° W

Photo 4. View of erosion forming along the access road. Additional stabilization/Stormwater controls area needed to minimize degradation along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08883