

## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



Entrance to location - Photo #05690



Wellheads - Photo #05691



**Inspection Photos**  
**Location: LARAMIE ENERGY LLC DAVID/23-7 PAD**  
**Location ID: 334500**  
**Date: 9/12/2024**



**Wellheads - Photo #05693**



**Wellheads - Photo #05694**

## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



Separators - Photo #05696



Separators - Photo #05697



## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



Separators - Photo #05698



Separators - Photo #05699

## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



Tank battery - Photo #05704



Location - Photo #05705



## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



NE corner of location - Photo #05732



SE corner of location - Photo #05733

## Inspection Photos

Location: LARAMIE ENERGY LLC DAVID/23-7 PAD

Location ID: 334500

Date: 9/12/2024



Wildlife hazard - Photo #05730



Shut in - Photo #05700

