

# Inspection Photos

API: 071-06400

Operator: OGRIS OPERATING LLC

Inspection Date: 9/16/2024

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing south along the access road to the abandoned wellsite. The culverts will need to be removed and the road recontoured.





## Inspection Photos



**Photo 2.** Facing southwest toward the abandoned wellsite. The access road and location will need to be recontoured and reclaimed.





## Inspection Photos



**Photo 3.** Facing southwest toward the abandoned wellsite. There is a SCADA tower that will need to be relocated. All other equipment appears to have been removed.





## Inspection Photos



**Photo 4.** Facing southeast at the location..

