

Bayless
Dry Creek 3-22
Location ID: 316758



Location



Location

Bayless
Dry Creek 3-22
Location ID: 316758



Location



Location

Bayless
Dry Creek 3-22
Location ID: 316758



Staining



Tank plug leaking

Bayless
Dry Creek 3-22
Location ID: 316758



Location



Location

Bayless
Dry Creek 3-22
Location ID: 316758



Improperly marked anchor



Separator has noticeable bird protector while heat treater is unknown