

Inspection Photos

Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad

Location #: 414530



Photo # 9946 From Entrance to location



Photo # 9947 From entrance to location

Inspection Photos

Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad

Location #: 414530




Photo # 9948 Location

Photo # 9949 Location

Inspection Photos

Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad

Location #: 414530



Photo # 9950 Location



Photo # 9951 Location

Inspection Photos
Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad
Location #: 414530



Photo # 9952 Location



Photo # 9953 Location

Inspection Photos
Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad
Location #: 414530



Photo # 9954 Location



Photo # 9955 Location

Inspection Photos

Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad

Location #: 414530



Photo # 9956 Location



Photo # 9957 Location

Inspection Photos
Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad
Location #: 414530



Photo # 9958 Location



Photo # 9959 Location

Inspection Photos
Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad
Location #: 414530




Photo # 9960 Location



Photo # 9961 Stained soils on location

Inspection Photos

Location Name: QB ENERGY SHIDELER 25-9C1 (C31E) Pad

Location #: 414530



Photo # 9962 Stained soils on location