

Inspection Photos
Location Name: Elmer Kaufman 2
API # 05-123-07611



Sign



Inspection Photos
Location Name: Elmer Kaufman 2
API # 05-123-07611



Safety Fence around the open hole needs to be repaired.



Safety Fence around the open hole needs to be repaired.