

Inspection Photos
Location Name: Kaufman 4
API # 05-123-07952



Sign & Overgrown vegetation



Inspection Photos
Location Name: Kaufman 4
API # 05-123-07952



Overgrown vegetation



Safety Fence around the open hole needs to be repaired.