


(SUBMIT IN DUPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

RECEIVED

JUN 18 1970

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

COLO. OIL & GAS CONS. COMM.

October 4, 1962

Well No. 1. W. is located 260 ft. from ☒ line and 320 ft. from ☒ line of sec. 4

Lot 14 Sec. 4 1 North 102 W. 6th P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Rangely Rio Blanco Colorado
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To test the Mancos shale

A shallow well



Approved 10/12/62

[Signature]
District Engineer

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WILLIAM G. WALDECK

Address P. O. Box 359

Montrose, Colorado

By William G. Waldeck

Title