


**Inspection Photos**  
**Location Name: Jones 2**  
**API Number: 125-07102**



**1. Well sign on meter shed. Sign is unreadable and requires replacement.**



**2. View of wellhead.**

**Inspection Photos**  
**Location Name: Jones 2**  
**API Number: 125-07102**



**3. Gas meter and vertical separator inside shed.**



**4. Produced water tank at well location.**

**Inspection Photos**  
**Location Name: Jones 2**  
**API Number: 125-07102**



**5. Erosion channel that starts above wellhead and flows towards meter shed.**



**6. Erosion channel at front of meter shed.**

**Inspection Photos**  
**Location Name: Jones 2**  
**API Number: 125-07102**



**7. Erosion channel that has cut through berm wall.**



**8. Channel coming through fencing and flowing down grade off location.**