

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403926380

Date Received:

09/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904581

Inspection Date: 09/11/2024

FIR Submit Date: 09/15/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334693

Location Name: COUEY-67S93W Number: 24SENW County: _____

Qtrqtr: SENW Sec: 24 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.434340 Longitude: -107.727120

FACILITY - API Number: 05-045-00 Facility ID: 334693

Facility Name: COUEY-67S93W Number: 24SENW

Qtrqtr: SENW Sec: 24 Twp: 7S Range: 93W Meridian: 6

Latitude: 39.434340 Longitude: -107.727120

CORRECTIVE ACTIONS:

1 CA# 198777

Corrective Action: Comply with CECMC pressure safety device rules

Date: 09/22/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator
Comment: Installed vent cap. See photo

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 9/18/2024 1:03:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403926383	Vent cap installed.
-----------	---------------------

Total Attach: 1 Files