

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Entrance to location - Photo #05756



Wellheads - Photo #05757



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Wellheads - Photo #05767



Separators - Photo #05786



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Separators - Photo #05787



Separators - Photo #05788



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Separators - Photo #05789



Separators - Photo #05790

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Pig station - Photo #05791



Tank battery - Photo #05793




## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Location - Photo #05795



ECD - Photo #05812

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



SE corner of location - Photo #05814



NE corner of location - Photo #05818



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05770



Debris - Photo #05771



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05773



Debris - Photo #05775



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05776



Debris - Photo #05777



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05780



Debris - Photo #05807



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05880



Debris - Photo #05813



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Debris - Photo #05816



Debris - Photo #05817



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Wildlife hazard - Photo #05783



Wildlife hazard - Photo #05784



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-10 PAD

Location ID: 418985

Date: 9/17/2024



Open ended load line - Photo #05805

