

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Entrance to location - Photo #05823



Wellheads - Photo #05824

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Separators - Photo #05830



Separators - Photo #05831

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Separators - Photo #05833



Separators - Photo #05834

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Shut in - Photo #05835



Shut in - Photo #05836

Inspection Photos


Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Tank battery - Photo #05841



Location - Photo #05842

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



ECD - Photo #05856



TEG - Photo #05862

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



NW corner of location - Photo #05863



SW corner of location - Photo #05864

Inspection Photos


Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



SE corner of location - Photo #05865



Open ended load line - Photo #05850

Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/30-03 PAD

Location ID: 451421

Date: 9/17/2024



Open ended load line - Photo #05851



Debris - Photo #05866