

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403927183

Date Received:
09/19/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:
7 of 7 CAs from the FIR responded to on this Form
7 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10776
Name of Operator: CROWHEART ENERGY LLC
Address: 1225 17TH STREET SUITE 2950
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Cathi Boles</u>	<u>303-268-5583</u>	<u>c.boles@crowheartenergy.com</u>
<u>.Regulatory</u>		<u>regulatory@crowheartenergy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500587
Inspection Date: 08/27/2024 FIR Submit Date: 08/27/2024 FIR Status: _____

Inspected Operator Information:

Company Name: CROWHEART ENERGY LLC Company Number: 10776
Address: 1225 17TH STREET SUITE 2950
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 313092

Location Name: BLUE SKY-69N91W Number: 1SESE County: MOFFAT
Qtrqtr: SESE Sec: 1 Twp: 9N Range: 91W Meridian: 6
Latitude: 40.762200 Longitude: -107.544920

FACILITY - API Number: 05-081- -00 Facility ID: 223584

Facility Name: BLUE SKY Number: 1-44
Qtrqtr: SESE Sec: 1 Twp: 9N Range: 91W Meridian: 6
Latitude: 40.762200 Longitude: -107.544920

CORRECTIVE ACTIONS:

1 CA# 198003

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor. Date: 09/11/2024

Response: CA COMPLETED Date of Completion: 09/11/2024

Operator Comment: Rig anchor marker was replaced.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 CA# 198004

Corrective Action: All equipment not hooked up or out of service will be removed from location.

Date: 09/12/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator
Comment:

All equipment not hooked up or out of service has been removed from location.

All equipment not hooked up or out of service has been removed from location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

3 CA# 198005

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator
Comment:

All excess materials, rubbish, supplies, trash and other waster material was removed from the Oil and Gas Location.

All excess materials, rubbish, supplies, trash and other waster material was removed from the Oil and Gas Location.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

4 CA# 198006

Corrective Action: Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.

Date: 09/12/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator
Comment:

Protective caps were replaced on vertical vent risers.

Protective caps were replaced on vertical vent risers.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

5 CA# 198007

Corrective Action: Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.

Date: 09/04/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator
Comment:

Weeds were removed from the pad area.

Weeds were removed from the pad area.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

6 CA# 198008

Corrective Action: All Tanks and Containers will be labeled pursuant to Rule 605. h. (1). All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.

Date: 09/27/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator Comment: All Tanks and Containers have been labeled pursuant to Rule 605.h.(1). All tanks with a capacity of 10 barrels or greater have been labeled or posted with the following information: Name of Operator, Operator's Emergency Contact Telephone Number, Tank Capacity, Tank contents, and NFPA label or equivalent globally harmonized label.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

7 CA# 198009

Corrective Action: Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.

Date: 09/07/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator Comment: All Tanks and Containers have been labeled pursuant to Rule 605.h.(1). All tanks with a capacity of 10 barrels or greater have been labeled or posted with the following information: Name of Operator, Operator's Emergency Contact Telephone Number, Tank Capacity, Tank contents, and NFPA label or equivalent globally harmonized label.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All debris and unused equipment has been picked up and removed from the location. All tanks and containers have been labeled pursuant to Rule 605.h.(1). Weeds have been removed from the pad area. Guy line anchor markers have been replaced. Protective caps have been replaced on relief risers.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathi Boles

Signed: _____

Title: Regulatory Manager

Date: 9/19/2024 9:08:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403927183	FIR RESOLUTION SUBMITTED
403927252	Photo of Condensate Tank
403927254	Photo of Methanol Tank
403927256	Photo of Produced Water Tank
403927258	Pad Photo 1
403927259	Pad Photo 2
403927260	Pad Photo 3
403927261	Pad Photo 4
403927262	Pad Photo 5

403927264	Pad Photo 6
403927265	Photo of Access to Pad
403927266	Photo of Guy Line Anchor Marker

Total Attach: 12 Files