

Inspection Photos

Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD

Location ID: 334539

Date: 9/17/2024



Wellheads - Photo #05877



Wellheads - Photo #05878

Inspection Photos

Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD

Location ID: 334539

Date: 9/17/2024



Separators - Photo #05880



Separators - Photo #05881

Inspection Photos

Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD

Location ID: 334539

Date: 9/17/2024



Sep 17, 2024 at 3:07:08 PM
+39.257535,-107.869943 ±4.74m

Tank battery - Photo #05887



Sep 17, 2024 at 3:09:05 PM
+39.257427,-107.869965 ±4.73m
Collbran

LARAMIE ENERGY LLC
SESW Sec 22 T9S R94W
Accessed from County Road 330E,
Mesa County, CO
Emergency Contact 1-800-891-6191 or 911
WELLS SERVICED BY THIS TANK BATTERY

Ute Water 22-10	05-077-09151	SESW Sec 22 T9S R94W
Ute Water 22-11	05-077-09150	SESW Sec 22 T9S R94W
Ute Water 22-12	05-077-09149	SESW Sec 22 T9S R94W

Ute Water 22-13	05-077-09148	SESW Sec 22 T9S R94W
Ute Water 22-14	05-077-09147	SESW Sec 22 T9S R94W
Ute Water 22-15	05-077-09146	SESW Sec 22 T9S R94W
Ute Water 27-2	05-077-09145	SESW Sec 22 T9S R94W
Ute Water 27-3	05-077-09144	SESW Sec 22 T9S R94W

Location - Photo #05890

Inspection Photos
Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD
Location ID: 334539
Date: 9/17/2024



NE corner of location - Photo #05912



NW corner of location - Photo #05913

Inspection Photos

Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD

Location ID: 334539

Date: 9/17/2024



SW corner of location - Photo #05915



Wildlife hazard - Photo #05903

Inspection Photos


Location: LARAMIE ENERGY LLC UTE WATER/22-14 PAD

Location ID: 334539

Date: 9/17/2024



Wildlife hazard - Photo #05910



Label peeling - Photo #05897