

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 9/19/2024



Wellheads – Photo #03507



Separators – Photo #03508

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 9/19/2024



Tank Battery – Photo #03510



Wellhead/Gas Meter – Photo #03513

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, HOAGLUND-67S95W/2NWNW

Location ID: 334724

Date: 9/19/2024



Unmarked Deadman – Photo #03512



Trash – Photo #03511