

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 9/19/2024



Location Entrance – Photo #03523



Wellheads – Photo #03527

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 9/19/2024



Separators – Photo #03532



Tank Battery – Photo #03528

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/3NWNW

Location ID: 334598

Date: 9/19/2024



Unsecured Separator – Photo #03530



Lack of Stabilization – Photo #03526