

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Entrance to location - Photo #05995



Wellheads - Photo #05996

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Separators - Photo #06001



Separators - Photo #06002



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Separators - Photo #06003



Separators - Photo #06004

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Separators - Photo #06005



Tank battery - Photo #06007



**Inspection Photos**  
**Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD**  
**Location ID: 450842**  
**Date: 9/18/2024**



**Location - Photo #06009**




**TEG - Photo #06046**

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Sep 18, 2024 at 1:09:24 PM  
+39.262569,-107.814834 ±4.73m

ECD - Photo #06049



Sep 18, 2024 at 1:11:04 PM  
+39.262435,-107.815055 ±4.75m

SW corner of location - Photo #06050



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



NW corner of location - Photo #06051



Wildlife hazard - Photo #06042

## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Open ended load line - Photo #06029



Open ended load lines - Photo #06030



## Inspection Photos

Location: LARAMIE ENERGY LLC BRUTON/19-06 PAD

Location ID: 450842

Date: 9/18/2024



Debris - Photo #06038



Debris - Photo #06039