

Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Hancock M 1 API: 009-06270



1. Location overview



2. Water tank and pumping unit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp #715200980

Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Hancock M 1 API: 009-06270



3. Meter shed west of wellhead



4. Casing valve is broken