

Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Hume C 1 API: 009-06242



1. Location overview



2. Weeds around water tank and unit



Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Hume C 1 API: 009-06242



3. Water leg corrosion



4. Meter shed and separator on west side of location



Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Hume C 1 API: 009-06242



5. Meter shed with lease sign that's faded

