

Inspection Photos
Location Name: GREENMEIER 9-30
Location ID: 319876



Photo#1 PRODUCTION TANKS

Photo#2 (2) VERTICAL SEPERATORS


Inspection Photos
Location Name: GREENMEIER 9-30
Location ID: 319876



Photo#3 PUMPJACK/WELLHEAD

Photo#4 PIT
(2) DUMPED REFRIGERATORS

Inspection Photos
Location Name: GREENMEIER 9-30
Location ID: 319876



Photo#5 FLOWLINE DISTANCE ~142'