

TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919




Disconnected Production Tanks relabeled "Fresh Water"




Debris



TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919



Debris



Debris



**TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919**



**Hole in liner**



**Debris**

TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919



**Disconnected Production Water tanks**



**Disconnected Condensate tank**



TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919



**Separator antifreeze drain valve missing plug**



**Separator antifreeze drain valve missing plug**



**TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919**



**Location from Northwest corner**



**Location from Southwest corner**



**TEP Rocky Mountain LLC  
Federal RGU 41-1-298  
Location ID: 335919**



**Location from Southeast corner**



**Location from Northeast corner**