

Inspection Photos

September 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326568

Inspection Document #: 714001239

La Plata County, CO

Township: NWNE 36 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State 1-36, 35-8 3
Location ID: 326568

9/18/24
+37.262624,-107.691998
18° N



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: State 1-36, 35-8 3
Location ID: 326568



Photo 2. View of the eastern interim reclamation area facing north.

Inspection Photos

Location Name: State 1-36, 35-8 3

Location ID: 326568



Photo 3. Patch of Musk thistle observed in the cut slope portion of the disturbance.



Inspection Photos

Location Name: State 1-36, 35-8 3

Location ID: 326568



9/18/24
+37.262986,-107.691679
5° N

Photo 4. Reference area comprised of Gambel oak, Pine and Smooth brome.

