

# Inspection Photos

September 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306928

Inspection Document #: 714001241

La Plata County, CO

Township: SWNE 1 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Burkett A2  
Location ID: 306928

9/18/24  
+37.245429,-107.692839  
7° N



Photo 1. View of the well pad taken from the access point facing center.





Inspection Photos  
Location Name: Burkett A2  
Location ID: 306928



**Photo 2.** View of large patch of Canada thistle observed in the western interim reclamation area.



Inspection Photos  
Location Name: Burkett A2  
Location ID: 306928



**Photo 3.** View of impacted surface material observed at the well head.





9/18/24  
+37.246040,-107.692825  
38° NE





Inspection Photos  
Location Name: Burkett A2  
Location ID: 306928



**Photo 5.** Evidence of sediment transport/deposition coming off the bare cutslope.



Inspection Photos  
Location Name: Burkett A2  
Location ID: 306928



9/18/24  
+37.246049,-107.693028  
273° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area comprised of Pine, Juniper and Sagebrush.

API #: 067-09062