

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 1: Location from entrance



Photo 2: Debris

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 3: Debris

Photo 4: Debris

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 5: Wrong wellhead name

Photo 6: Pumpjack

Location Name: Pioneer 14, 19, 23, 35-2
Location ID: 336452



Photo 7: Debris

Photo 8: Wrong wellhead name

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 9: Debris



Photo 10: Pumpjack, fencing in disrepair

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 11: Debris

Photo 12: Wrong wellhead name

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 13: Pumpjack

Photo 14: Fencing in disrepair

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Energy & Carbon Management Commission
40.09819, -104.94415, 1505.5m, 99°
Sep 19, 2024 09:34:16



Energy & Carbon Management Commission
40.0982, -104.94425, 1504.9m, 63°
Sep 19, 2024 09:35:51

Photo 15: Wrong wellhead name

Photo 16: Pumpjack

Location Name: Frederick Unit A1, B1, C1, D1
Location ID: 336452



Photo 17: Fencing in disrepair

Photo 18: Fencing in disrepair