

Inspection Photos

September 19th, 2024

Operator: Alamosa Drilling Inc. - 900

Location ID: 320916

Inspection Document #: 714001257

Archuleta County, CO

Township: NENW 19 32N 1E N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Martinez A2
Location ID: 320916

9/19/24
+37.003957,-106.887148
116° SE



Inspection Photos
Location Name: Martinez A2
Location ID: 320916



Inspection Photos
Location Name: Martinez A2
Location ID: 320916



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: grazed vegetation appears to be dominated by desirable species including Grama sp. and Smooth brome and Rose.

Inspection Photos
Location Name: Martinez A2
Location ID: 320916



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Large patch of Musk thistle observed at the access point of the disturbance, approximately 30 individuals observed.

API #: 007-06257

Inspection Photos
Location Name: Martinez A2
Location ID: 320916



Photo 5. Reference area comprised of Pine and Gambel oak with an understory of Smooth brome and Grama sp.