

Inspection Photos
Location Name: CHAMPLIN 67 AMOCO D1
Location ID: 319852



Photo #1 Tanks.



Photo #2 Weeds in, on and around tank berms.

Inspection Photos
Location Name: CHAMPLIN 67 AMOCO D1
Location ID: 319852



Photo #3 Separator and Meter house.



Photo #4 Pump jack and weeds around pump jack.