

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403929752

Date Received:

09/20/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Josh Knigge

307-259-7834

joshk@kirkwoodcompanies.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500655

Inspection Date: 09/13/2024

FIR Submit Date: 09/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: WESCO OPERATING INC

Company Number: 95520

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

LOCATION - Location ID: 332715

Location Name: MAUDLIN GULCH UNIT-64N95W Number: 27NESE County: _____

Qtrqr: NESE Sec: 27 Twp: 4N Range: 95W Meridian: 6

Latitude: 40.283988 Longitude: -108.029782

FACILITY - API Number: 05-081-00 Facility ID: 332715

Facility Name: MAUDLIN GULCH UNIT-64N95W Number: 27NESE

Qtrqr: NESE Sec: 27 Twp: 4N Range: 95W Meridian: 6

Latitude: 40.283988 Longitude: -108.029782

CORRECTIVE ACTIONS:

1 ☒ CA# 198766

Corrective Action: All equipment not hooked up or out of service will be removed from location.

Date: 09/28/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: All unused equipment was removed from location.

ECMC Decision: Approved pending re-inspection

ECMC Representative:			
----------------------	--	--	--

2	<input checked="" type="checkbox"/>	CA# 198767	
----------	-------------------------------------	-------------------	--

Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date: <u>04/06/2024</u>
--------------------	--	-------------------------

Response:	CA COMPLETED	Date of Completion: <u>09/17/2024</u>
-----------	--------------	---------------------------------------

Operator Comment:	Chemical container and containment was removed from location.
-------------------	---

ECMC Decision:	Approved pending re-inspection
----------------	--------------------------------

ECMC Representative:	
----------------------	--

3	<input checked="" type="checkbox"/>	CA# 198768	
----------	-------------------------------------	-------------------	--

Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date: <u>09/20/2024</u>
--------------------	---	-------------------------

Response:	CA COMPLETED	Date of Completion: <u>09/17/2024</u>
-----------	--------------	---------------------------------------

Operator Comment:	All debris removed from location.
-------------------	-----------------------------------

ECMC Decision:	Approved pending re-inspection
----------------	--------------------------------

ECMC Representative:	
----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:	See attached photos.
----------	----------------------

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: <u>Josh Knigge</u>	Signed: _____
Title: <u>Operations Tech</u>	Date: <u>9/20/2024 3:29:38 PM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403929752	FIR RESOLUTION SUBMITTED
403929759	MG #27 inspection pics

Total Attach: 2 Files