

Inspection Photos

API: 099-06881

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/24/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. The berm has been built up better for secondary containment and netting has been placed over the tank. Labels are posted on the tank.

