

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 9/24/2024



**Location Entrance – Photo #03590**



**Wellheads – Photo #03591**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 9/24/2024



Separators – Photo #03599



ECD – Photo #03601

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 9/24/2024



**Ancillary Equipment – Photo #03600**



**Unstabilized Cut Slope – Photo #03603**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP/21-20-695

Location ID: 335116

Date: 9/24/2024



**Unstabilized Cut Slope – Photo #03604**