


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/21SWNW

Location ID: 335257

Date: 9/24/2024



Wellheads – Photo #03627



Separators – Photo #03624

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, DOE-66S95W/21SWNW

Location ID: 335257

Date: 9/24/2024



Gas Meter – Photo #03625



Tank Battery – Photo #03626