

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 9/24/2024



Sep 24, 2024 at 12:48:54
Parachute CO 81635
United States

Location Entrance – Photo #03632



Sep 24, 2024 at 12:49:36
Parachute CO 81635
United States

Wellheads – Photo #03633

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 9/24/2024



Sep 24, 2024 at 12:50:17
Parachute CO 81635
United States

Wellheads – Photo #03634



Sep 24, 2024 at 12:52:14
Parachute CO 81635
United States

Separators – Photo #03638

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 9/24/2024



Tank Battery – Photo #03640



Unstabilized Cut Slope – Photo #03647

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 9/24/2024



Unstabilized Cut Slope – Photo #03648



Cut Slope Eroding onto Access Road – Photo #03649