

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/11SESE

Location ID: 324305

Date: 9/23/2024



Entrance to location - Photo #06150



Location - Photo #06190

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/11SESE

Location ID: 324305

Date: 9/23/2024



Location - Photo #06151



Location - Photo #06154

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/11SESE

Location ID: 324305

Date: 9/23/2024



Location - Photo #06162



NE corner of location - Photo #06174

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/11SESE

Location ID: 324305

Date: 9/23/2024



SE corner of location - Photo #06175



Hole in containment liner - Photo #06164

Inspection Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/11SESE

Location ID: 324305

Date: 9/23/2024



No labeling - Photo #06172



Wildlife hazard - Photo #06187