

Inspection Photos

September 25th, 2024

Operator: American Helium Operating - 10841

Location ID: 322096

Inspection Document #: 714001269

Dolores County, CO

Township: SENE 18 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Santa Fe Canyon Federal 42-18
Location ID: 322096

9/25/24
+37.839737,-109.462326
199° S



Photo 1. View of the well pad taken from the access point facing center.



API #: 033-06063



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Santa Fe Canyon Federal 42-18
Location ID: 322096

9/25/24
+37.839737,-109.462326
185° S



Photo 2. Tank label needs to be updated, weedy debris impacting secondary containment/berm integrity and needs to be removed.



Inspection Photos

Location Name: Santa Fe Canyon Federal 42-18

Location ID: 322096



Photo 3. Weedy debris/vegetation is affecting secondary containment/berm integrity and needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 033-06063

Inspection Photos

Location Name: Santa Fe Canyon Federal 42-18

Location ID: 322096

9/25/24

+37.839737,-109.462326

329° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of western interim reclamation area that appears consistent with adjacent reference area.

API #: 033-06063

Inspection Photos
Location Name: Santa Fe Canyon Federal 42-18
Location ID: 322096



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of Juniper, Crested wheatgrass and Broom snakeweed.

API #: 033-06063